PROJECT: SRMS
ASS'Y HOMENCLATURE: DEC PANEL

FMEA FMEA	DRAWING REF. DESIGNATION	FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	/ func. RATIONALE FOR ACCEPTANCE 2/1R CRITICALITY SCREENS: A-PASS, B-PASS, C-PASS
1220 1	VOLTAGE DETECTION CIRCUIT QTY-1 ED94385	MODE: CONTINUOUS SAFING SIGNAL. CAUSE(S): (1) INTERNAL PARIS FAILURE. (2) K6 CONTACT O/C.	OV TO SAFING LINE. ARM IN HARDWIRE SAFING. LOSS OF LIMPING DURING END EFFECTOR CAPTURE. WORST CASE LOSS OF MISSION. LOSS OF COMPUTER SUPPORTED HODES. REDUNDANT PATHS REMAINING DIRECT AND BACKUP	DESIGN FEATURES THE VOLTAGE DETECTION CIRCUIT UTILIZES ONLY THREE "ACTIVE" EEE PARTS: TWO TRANSISTORS, TYPE ZW222ZA, AND A RELAY. THE RELAY IS PROCURED TO MIL-R-39016 AND SCREEMED TO THE REQUIREMENTS OF MASS ST.R-DOOT. THE RELAY IS MOUNTED ON A PRINTED CIRCUIT BOARD WHICH HAS A FULL WIDTH MACHINED ALUMINIUM SUPPORT FRAME. THE FRAME ENGAGES IN MACHINED GUIDEWAYS IN THE ELECTRONICS PACKAGE. THIS COMPIGURATION ENURSES GOOD VIBRATION DAMPING AND HEAT TRANSFER. EEE PARTS HAVE BEEN SELECTED AND CONTROLLED IN ACCORDANCE WITH SPAR-RMS-PA.003. THIS DOCUMENT DEFINES THE PROGRAM REGUIREMENTS FOR MONITORING AND CONTROLLING EEE PARTS. THE REQUIREMENTS FOR MONITORING AND CONTROLLING EEE PARTS. THE REQUIREMENTS INCLUDE PARTS SELECTION TO AT LEAST "ESTABLISHED RELIABILITY" LEVELS, AND ADEQUATE DERATING OF PART STRESS LEVELS. PROCEDURES AND ACTIVITIES ARE SPECIFIED TO ENSURE AT LEAST EQUIVALENT QUALITY FOR NOMSTANDARD AND IRREGULAR PARTS. RELIABILITY MALAYSIS HAS CONFIRMED NO PARTS WITH GENERICALLY RIGHT SHALLOW AND ALLOW THE MET SHALLOW AND STRUCTURAL/MECHANICAL/INTEGRITY OF ASSEMBLIES ARE APPLIED. SUCH DESIGN HAD SERVE EVISUED AND FOUND SATISFACTORY THROUGH THE OSSIGN AND SHALLOW FOR MACHINITY HAD SAFETY CHECKLISTS. MATERIAL SELECTION AND USAGE CONFORMS TO SPAR-SC.JSB MITCH IS EQUIVALENT TO THE MASA MATERIALS USAGE REQUIREMENTS. WORST CASE ANALYSIS MAS BEEN CONFORTS TO SPAR-SC.JSB MITCH IS EQUIVALENT TO THE MASA MATERIALS USAGE REQUIREMENTS. WORST CASE ANALYSIS HAS BEEN CONFORTED AND CONFIRM APPROPRIATE DIMENSIONS OF CIRCUIT SOLDER PARTS STRESS ANALYSIS HAS BEEN CONFOLETED AND COMFIRM APPROPRIATE DIMENSIONS OF CIRCUIT SOLDER PADS AND OF COMPONENT HOLD PROVISIONS. PARTS MOUNTING METHODS ARE CONTROLLED IN ACCORDANCE MITH MSFC-SID-136 AND CASE POPSIABP. THESE DOCUMENTS REQUIRE APPROVED-MOUNTING METHODS, SIRESS RELIEF, AND COMPONENT SECURITY. UNERE APPLICABLE, DESIGN DRAWINGS AND DOCUMENTATION GIVE CLEAR IDENTIFICATION OF MANDLING PRECAUTIONS FOR ESD SENSITIVE PARTS. BOAND ASSEMBLY DRAWINGS INCLUDE THE REQUIREMENT FOR SOLDER

HEA FMEA REV.	HAME, QTY, B DRAWING REF. DESIGNATION	FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	HDWR / FUHC. RATIONALE FOR ACCEPTANCE 2/1R CRITICALITY SCREENS: A-PASS, B-PASS, C-PASS
1220	VOLTAGE DETECTION CIRCUIT OTY-1 ED94385	MODE: CONTINUOUS SAFING SIGNAL. CAUSE(S): (1) INTERNAL PARIS FAILURE. (2) K6 CONTACT D/C.	OV TO SAFING LINE. ARM IN HARDWIRE SAFING. LOSS OF LIMPING DURING END EFFECTOR CAPTURE. WORST CASE LOSS OF MISSION. LOSS OF COMPUTER SUPPORTED MODES. REDUNDANT PATHS REMAINING DIRECT AND BACKUP	ACCEPTANCE TESTS THE HARDWARE ITEM IS SUBJECTED TO THE FOLLOWING ACCEPTANCE ENVIRONMENTAL TESTING AS PART OF THE DAC PANEL. O VIBRATION: LEVEL AND DURATION - REFERENCE TABLE 1 O THERMAL: +100 DEGREES F TO +10 DEGREES F 2 CYCLES (9.3 MAS PER CYCLE) THE DAC PANEL ASSEMBLY IS FURTHER TESTED AS PART OF THE RMS SYSTEM (1P518 MMS STRONGBACK TEST AND TP522 FLAT FLOOR TEST) WHICH VERTIES THE ABSENCE OF THE FAILURE MODE. GUALIFICATION TESTS THE DAC PANEL HAS BEEN SUBJECTED TO THE FOLLOWING QUALIFICATION TEST ENVIRONMENT: O VIBRATION: LEVEL AND DURATION - REFERENCE TABLE 1 O SHOCK: 200/11MS - 3 AMES (6 DIRECTION) O THERMAL: 130 DEGREES F TO -23 DEGREES F (12 MRS PER CYCLE) (6 CYCLES) O HUMIDITY: 95X (120 DEGREES F TO 02 DEGREES F CYCLE IN 16 MRS) 10 CYCLES TOTAL O EMC: M11-STD-464 AS MODIFIED BY SL-E-DOD2 (TEST CEO1, CE CEO3, RSD2, RSD3, RSD4) RED2 (B/M) RSD2, D3, O4) FLIGHT CHECKOUT PORS OPS CHECKLIST (ALL VEHICLES) JSC 16987

PREPARED BY:

RITICAL ITEMS LIST			PROJECT: SRMS ASS'Y NOMENCLATURE: <u>DEC PAREL</u>			SYSTEM: DAC SUBSYSTEM ASS'Y P/N: 51140E391 SHEET:		
FMEA REF.	FHEA REV.	NAME, GTY & DRAWING REF. DESIGNATION	FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEN	HDWR / FUHC. 2/1R CRITICALITY	RATIONALE FOR ACCEPTANCE SCREENS: A-PASS, B-PASS, C-PASS		
1220		VOLTAGE DETECTION CIRCUIT GIV-1 ED94385	MODE: CONTINUOUS SAFING SIGMAL. CAUSE(S): (1) INTERNAL PARTS FAILURE. (2) K6 CONTACT O/C.	OV TO SAFING LINE. ARM IN HARDWIRE SAFING. LOSS OF LIMPING DURING END EFFECTOR CAPTURE. WORST CASE LOSS OF HISSION. LOSS OF COMPUTER SUPPORTED MODES. REDUNDANT PATHS REMAINING DIRECT AND BACKUP	SPAR-RMS-PA. TO THE REQUII PARTS ARE 10 REQUIRED BY EEE PARTS ARI REQUIREMENTS FACILITY. DP. SELECTED 5X EACH LOT NUM WIRE IS PROCE AND INSPECTED IDENTIFIED II DANAGE MAS OF RECEIVING DOWN AND SCREENIM PARTS ARE IN APPROPRIATE INSPECTIONS PRINTED CIRCI AND ADEQUACY COMPONENT MOD LOOPING. STR. AND CERTIFIES BY JSC 08800. COMFORMAL CO. PERFORMED US POST P.C. BD. WORKMANSHIP MATING, WIRE PRE-TEST INS OF LOWER TIE. VERIFICATION MANDATORY IN A TEST READ! TEST PERSONN VALIDATION S QUALITY ASSU RELIABILITY.	SPECTION IS PERFORMED AS REQUIRED BY DOS. EACH EEE PART IS QUALIFIED AT THE PART LEVEL REMENTS OF THE APPLICABLE SPECIFICATION. ALL EEE DOS. EACH EEE PART IS QUALIFIED AT THE PART LEVEL REMENTS OF THE APPLICABLE SPECIFICATION. ALL EEE DOS RESCREENED AND BURNED IN, AS A MINIMUM, AS E 100X RE-SCREENED IN ACCORDANCE WITH BY AN INDEPENDENT SPAR APPROVED TESTING A IS PERFORMED AS REQUIRED BY PA.003 ON A RANDONLY OF PARTS, MAXIMUM 5 PIECES, MINIMUM 3 PIECES FOR BER/DATE CODE OF PARTS RECEIVED. URED TO SPECIFICATION MIL-W-22759 OR MIL-W-813B1 D AND TESTED TO NASA JSCM808D STANDARD NUMBER 95A. SPECTION VERIFIES THAT ALL PARTS RECEIVED ARE AS N THE PROCUREKENT DOCUMENTS, THAT NO PHYSICAL CCURRED TO PARTS DURING SHEPMENT, THAT THE CUMENTS PROVIDE ADEQUATE TRACEABLITY INFORMATION G DATA CLEARLY IDENTIFIES ACCEPTABLE PARTS. SPECTED THROUGHOUT MANUFACTURE AND ASSEMBLY AS TO THE MANUFACTURING STAGE COMPLETED. THESE INCLUDE, UIT BOARD INSPECTION FOR TRACK SEPARATION, DAMAGE OF PLATED THROUGH HOLES, UNITING INSPECTION FOR CORRECT SOLDERING, WIRE APPING, ETC. OPERATORS AND INSPECTORS ARE TRAINED D TO MASA MHB 5300.4(3A) STANDARD, AS MODIFIED		

ACCEPTANCE TESTING (ATP) INCLUDES AMBIENT PERFORMANCE,

DATE: 24 JUL 91

CIL REV: _2

CRITICAL ITEMS LIST

PREPARED BY:

MFWG

PPOJECT: SRMS SYSTEM: DEC SUBSYSTEM NOMENCLATURE: DEC PANEL ASS'Y P/N: 51140E391 SHEET: NAME, QTY, & DRAWING REF. FHEA FHEA FAILURE MODE FAILURE EFFECT HDUR / FUNC. 2/18 RATIONALE FOR ACCEPTANCE REF. REV. CAUSE DESIGNATION END ITEM CRITICALITY SCREENS: A-PASS, B-PASS, C-PASS 1220 1 **VOLTAGE** OV TO SAFING LINE. ARM IN MODE: THERMAL AND VIBRATION TESTING, (SPAR/GOVERNMENT REP. -CONTINUOUS DETECTION MANDATORY INSPECTION POINT). CIRCUIT OTY-1 SAFENG HARDWIRE SAFING. LOSS OF INTEGRATION OF D&C PANEL, RHC, THC AND MCIU, INSPECTIONS ARE PERFORMED AT EACH STAGE OF INTEGRATION, WHICH INCLUDES GROUNDING CHECKS, INTER CONNECT CABLE VERIFICATION, CONNECTOR SIGNAL. ED94385 LIMPING DURING CAUSE(\$): END EFFECTOR (1) INTERNAL CAPTURE. INSPECTION FOR BENT OR PUSHBACK CONTACTS ETC. PARIS FAILURE. WORST CASE SUB-SYSTEM PERFORMANCE TESTING (ATP), INCLUDES AN AMBIENT PERFORMANCE TEST, (MANDATORY INSPECTION POINT). LOSS OF (2) K6 MISSION. LOSS OF COMPUTER SUPPORTED SMS SYSTEMS INTEGRATION, THE INTEGRATION OF MECHANICAL ARM SUBASSEMBLIES AND THE FLIGHT CABIN EQUIPMENT TO FORM THE SRMS. INSPECTIONS ARE PERFORMED AT EACH PHASE OF INTEGRATION WHICH CONFACT O/C. INCLUDES GROUNDING CHECKS, THRU WIRING CHECKS, WIRING ROUTING, INTERFACE CONNECTORS FOR BENT OR PUSH BACK CONTACTS ETC. MODES. REDUNDANT PATHS REMAINING SRMS SYSTEMS TESTING - STRONGBACK AND FLAT FLOOR AMBIENT PERFORMANCE TEST. (SPAR/GOVERNMENT REP. - MANDATORY INSPECTION DIRECT AND BACKUP

RMS/D&C - 244

APPROVED BY:

DATE: 24 JUL 91

CIL REV: 2

SUPERCEDING DATE: 06 OCT 87

CRITICAL ITEMS LIST

FMEA REF.	FMEA REV.	NAME, QTY, & DRAWING REF. DESIGNATION	FAILURE MODE AND CAUSE	FAILURE EFFECT ON END 1TEM	HDWR / FUNC. 2/1R ERITICALITY	RATIONALE FOR ACCEPTANCE SCREENS: A-PASS, B-PASS, C-PASS	
1220	•	VOLTAGE DETECTION CIRCUIT GIY-1 ED94385	MODE: CONTINUOUS SAFING SIGHAL. CAUSE(S): (1) INTERNAL PARTS FAILURE. (2) K6 CONTACT O/C.	OV TO SAFING LINE, ARM IN HARDWIRE SAFING, LOSS OF LIMPING DURING END EFFECTOR CAPTURE. WORST CASE LOSS OF MISSION, LOSS OF CONPUTER SUPPORTED MODES. REDUNDANT PATHS REMAINING DIRECT AND BACKUP	FAILURE HI		

RMS/D&C - 245

CRITICAL ITEMS LIST

PREPARED BY:

HFHG

PROJECT: SRMS ASS'Y NOMENCLATURE: DEC PANEL

SYSTEM: D&C SUBSYSTEM ASS'Y P/N: 51140E391

DATE: 24 JUL 91

CIL REV; 2

SHEET: FAILURE EFFECT HDWR / FUNC. 2/1R RATIONALE FOR ACCEPTANCE NAME, GTY, & DRAWING REF. FAILURE MODE FHEA FMEA REV. AHD ON REF. CAUSE END LIEM CRITICALITY SCREENS: A-PASS, B-PASS, C-PASS DESIGNATION 1220 **VOLTAGE** MODE: OV TO SAFING OPERATIONAL EFFECTS 1 LINE. ARM IN HARDWIRE CONTINUOUS DETECTION SAFING CIRCUIT COMPUTER SUPPORTED MODES CANNOT BE USED TO COMPLETE THE SAFING. LOSS OF SIGNAL. 911-1 MISSION. DIRECT DRIVE AND BACK-UP MODES REMAIN. IF PAYLOAD ATTACHED, THE ARM SHOULD BE MANEUVERED TO A SAFE POSITION FOR LIMPING DURING ED94385 CAUSE(S):" END EFFECTOR PAYLOAD RELEASE. LOSS OF MEXT REDUNDANT PATH RESULTS IN BEING ONE FAILURE AWAY FROM IMABILITY TO CRADLE ARM. (1) INTERNAL PARTS CAPTURE. IF WITH SUBSEQUENT FAILURES ALL DRIVE MODES ARE LOST, WORST CASE FAILURE. THE ARM MAY BE JETTISONED. LOSS OF (2) K6 MISSION. LOSS CONTACT O/C. OF COMPUTER SUPPORTED CREW ACTION MODES. USE DIRECT DRIVE REDUNDANT PATHS REMAINING CREW TRAINING DIRECT BACKUP NONE **MISSION CONSTRAINT** NONE OMRSD OFFLINE INITIATE AUTO SAFING. VERIFY HARDWIRE SAFING VOLTAGE AT D&C PANEL OUTPUT. OMRSD ONLINE INSTALLATION INITERTE AUTO SAFING FROM MCIU. VERIFY HARDWIRE SAFING VOLTAGE AT LONGERON INTERFACE. OMRSD ONLINE TURNAROUND INITIATE AUTO SAFING FROM MCIU. OPERATE ONE JOINT IN SINGLE. VERIFY NO JOINT MOTION.

SUPERCEDING DATE: 06 OCT 87

APPROVED BY: